



MONTHLY REPORT

AUGUST - 2024

ADMINISTRATOR

ROSSY A. ABARCA SALGADO

MAINTENANCE REPORT AUGUST 2024

1. Fumigación de termitas de la entrada del techo del edificio A.
1. Termites fumigation of the roof of the entrance of building A.




2. Fumigación de termitas del techo del lobby
2. Termites fumigation of lobby ceiling




- 3. Fumigación de termitas del pasillo y techo de la torre B
- 3. Termites fumigation of the hallway and roof of building B



- 4. fumigación de termitas del techo del deptto. 503 B.
- 4. Termites fumigation of the ceiling of unit 503 B.



- 5. fumigación de termitas del techo del deptto. 504 B
- 5. Termites fumigation of the ceiling of unit 504 B



6. Se cortaron las ramas de las plantas y limpio el área del vivero.
6. The plants were cut and the nursery area was cleaned.



7. Se compró e instaló una nueva bomba de riego porque se quemó debido al uso.
7. A new irrigation pump was purchased and installed because it burned out due to use.



8. Se removieron e instalaron nuevos focos para la alberca grande debido a que los que teníamos estaban descontinuados.
8. New lights were removed and installed for the big pool because the ones we had were discontinued.



9. Colocamos una puerta reutilizada debajo de la caceta de seguridad.
9. We place a reused door under the security booth.



10. fumigación contra serpientes en oficina de CVM.
10. Fumigation against snakes in the CVM office.



11. Instalación de nuevo cableado y cámara de seguridad en la entrada peatonal del condominio

11. Installation of new wiring and security camera at the pedestrian entrance of the condominium.



12. Reparación de fusibles quemados de bomba de riego.
12. Repair of blown irrigation pump fuses.



13. Instalación de tubería de cobre para bomba de riego.
13. Copper pipe installation for irrigation pump.




14. Se les dieron mantenimiento a los paneles solares.
14. The solar panels were maintained.



15. Reparación de tubo de la llave de regar en área de jardín de alberca grande.
15. Repair of a watering tap pipe in the big pool garden area.



16. Se reemplazaron vigas y duelas podridas del techo del departamento 501 A
16. Rotten beams and ceiling planks were replaced in unit 501 A



ADDITIONAL REPORT AUGUST 2024

1. Curso de capacitación de primeros auxilios para trabajadores CVM.
1. First aid training course for CVM workers.



2. Cumpleaños de Alejo guardia de seguridad y Armando jardinero.
2. Alejo's security guard and Armando's gardener birthday celebration.

